



Looking NE At Existing South Canopy



Looking East At North Drive



Looking East At South Canopy



Looking East At South Entry



Looking East At West Elevation



Looking NE



Looking West On South-Entry Side



Looking North At SW Exterior Corner

project number:
2016-02
date:
06/20/16

AS102.2

David B. Howell
Architecture & Design, P.C.
5148 North Calle Bujia
Tucson, Arizona 85718
V 520 299-8093
david@dbhad.com

EXISTING EXTERIOR CONDITIONS
GOODMAN CHILDCARE
1133 S. DOBSON ROAD, SUITE #101
MESA, ARIZONA 85202





Looking South - 1



Looking South - 2



Looking South - 3



Looking South - 4



Looking South - 5



Looking South - 6



Looking SW At East Play Yard



Looking South At East Play Yard



Looking SW At the Building

project number:
2016-02
date:
06/20/16

AS102.1

David B. Howell
Architecture & Design, P.C.
■ 5148 North Calle Buja
Tucson, Arizona 85718
■ V 520 299-8093
■ david@dbhad.com

EXISTING EXTERIOR CONDITIONS
GOODMAN CHILDCARE
1133 S. DOBSON ROAD, SUITE #101
MESA, ARIZONA 85202

