



Design Review Board





DRB24-00981 Downtown Façade 117-119 W. Main





Request

- Design Review
- Downtown façade improvement to existing storefront








Location

- South side of Main Street
- West of Center
 Street
- East of Country Club Drive







Site Photo




Looking south from Main Street





Site Plan

- Remove existing colonnade
- Demo existing storefront system and door
- Install new window wall system
- Install new overhead canopy
- Install new concrete







Elevations







Elevations







Material Board

EXTERIOR MATERIALS



MT-01

DESCRIPTION: Z-GIRT (OR SIMILAR) LIGHT GAUGE LOUVERS TYP. PRODUCT: B.O.D. PAC CLAD PERFORMANCE COATING FINISH/ COLOR: REGAL WHITE 614973; DARK BRONZE 614354



MT-02 DESCRIPTION: APPROX 6"X6" TUBE STEL FRAME WITH WELDED PLATE STEEL SURROUND PRODUCT: B.O.D. PAC CLAD PERFORMANCE COATING FINISH/ COLOR: REGAL WHITE 614973; DARK BRONZE 614354



MT-03

DESCRIPTION: SHEET METAL FLASHING, METAL ACCENTS, FENCE, GATES, PLANTERS PRODUCT: B.O.D. PAC CLAD PERFORMANCE COATING FINISH/ COLOR: MATCH ADJACENT OR DARK BRONZE 614354





PT-01

DESCRIPTION: PAINTED SMOOTH FINISH STUCCO PRODUCT: B.O.D. SHERWIN WILLIAMS FINISH/ COLOR: 6990 CAVIAR #4B4A4B

PT-02

DESCRIPTION: PAINTED SMOOTH FINISH STUCCO PRODUCT: B.O.D. SHERWIN WILLIAMS FINISH/ COLOR: 6002 **ESSENTIAL GRAY #BEBBB9**

PT-03

DESCRIPTION: PAINTED SMOOTH FINISH STUCCO PRODUCT: B.O.D. SHERWIN WILLIAMS FINISH/ COLOR: 7066 GRAY MATTERS #A7AAA7

PT-04

DESCRIPTION: PAINTED SMOOTH FINISH STUCCO PRODUCT: B.O.D. SHERWIN WILLIAMS FINISH/ COLOR: 2848 ROYCROFT PEWTER

GL-01

DESCRIPTION: NEW STOREFRONT SYSTEM PRODUCT: B.O.D. VIRACON VE3-2M FINISH/ COLOR: MATCH EXISTING LE STUDIO OR TRE

DESCRIPTION: ALUMINUM FRAMING, WINDOW PRODUCT: B.O.D. HIGH PERFORMANCE FLUOROPOLYMER FINISH/ COLOR: MATCH EXISTING LE STUDIO OR





Findings

Staff is seeking your review and recommendation on the following:

✓ Proposed façade improvement

Staff welcomes any feedback





Design Review Board






- REPAIR AND REPAINT STUCCO
 TYP. ALL
- 2. EXPOSE EXISTING CORRUGATIONS
- 3. ~6X6 TUBE STEEL FRAME
- 4. WALL SCONCE(S)
- 5. NEW STOREFRONT SYSTEM
- STEEL SHADE CANOPY SYSTEM (~6X6 STEEL TUBE WITH LIGHT GAUGE LOUVERS)
- 7. "ROPE LIGHT" OR SIMILAR

 AROUND INSIDE OF FRAME TYP.
- 8. METAL PANEL INSIDE FRAME
- 9. METAL PLANTER BOXES
- 10.BENCH
- 11. SLIDING GLASS STOREFRONT SYSTEM
- 12.NEW STEEL COLUMNS TO

 UTILIZE EXISTING FOOTINGS IF

 POSSIBLE
- 13. STEEL CABLES
- 14. STEEL PLANTER BOX







Context Photos



