



Design Review Board





DRB25-00399 Sun Devil Auto





Request

- Design Review
- To allow for a
 Minor
 Automobile/Vehic
 le Service and
 Repair facility







Location

- 280± ft east of Signal Butte Road
- North side of Southern Avenue







Site Photo




Looking north from Southern Avenue





Site Plan

- Building Area: 7,689 SF
- Bay doors on the east elevation
- Shared access from Signal Butte Road and Southern Avenue
- 26 Parking Spaces





PLANT SCHEDULE

SCIENTIFIC NAME



PLANNING

12000

14000

3600

6600

720

39720

40%

MATURE SIZE

Deciduous, 40' x 35

Evergreen, 10' x 8'

TOTAL SITE CANOPY IN S.F.

SITE CANOPY PERCENTAGE

10' x 10'

10' x 10'

3' x 5'

3' x 5'


2' x 3'

2' x 2'

4' x 5'

3' x 3'

Landscape Plan







Building Elevations



29.3%

55.9 SF 4.7%

550.3 SF 46.7% 57.6 SF

4.8%

7.8%

0 SF 0%

METAL (SIGN)

BRICK - VENEER

PAINTED STUCCO

CMU, SPLITFACE, SW-9173

CMU, SPLITFACE, SW-7025

0 SF 0%

909.8 SF

1,140.4 SF 32.3%

424.4 SF

12.0%

996.5 SF

716.8 SF 20.3%

5.0%

228.6 SF 6.5%





Building Elevations



482.2 SF 40.7%

55.9 SF

METAL (SIGN)
BRICK - VENEER

CMU, SPLITFACE, SW-9173

233.3 SF 6.6%

> 25.8% 1.140.4 SF





Building Elevations



| LEGEND - FINISHES / SURFACES | | | | | |
|------------------------------|-------------------------|-------------------|-------------------|-------------------|---------------------|
| LEGEND DESC | DESCRIPTION | N | S | E | W |
| | | 1,176.5 s.f. | 1,183.4 s.f. | 3,514.6 s.f. | 3,525.5 s.f. |
| | METAL (SIGN) | 0 SF 0% | 482.2 SF 40.7% | 233.3 SF 6.6% | 0 SF 0% |
| | BRICK - VENEER | 345.8 SF 29.3% | 260.9 SF 22.0% | 209.2 SF 5.9% | 909.8 SF 25.8% |
| | CMU, SPLITFACE, SW-9173 | 55.9 SF 4.7% | 57.6 SF 4.8% | 716.8 SF 20.3% | 1,140.4 SF 32.3% |
| | CMU, SPLITFACE, SW-7025 | 182.0 SF 15.4% | 93.0 SF 7.8% | 177.1 SF 5.0% | 424.4 SF 12.0% |
| | PAINTED STUCCO | 550.3 SF 46.7% | 0 SF 0% | 228.6 SF 6.5% | 996.5 SF 28.2% |





Rendering








Rendering







Colors and Materials



Rojo Dust

CUSTOM BRAND COLOR - PER OWNER

7621 C

GENERAL NOTES - EL EVATION

- A EXTERIOR SEALANT SHALL MATCH COLOR OF CMU
- B INSTALL CONTROL JOINTS PER MFR RECOMMENDAT
- C ALL SIGNAGE WILL BE PERMITTED SEPARA
- D. COORDINATE ANY REQUIRED KNOX BOXES WITH SHUFFIRE MARSHALL FOR TYPE AN
- E PRIME ALL CMU BEFORE PAINTING OR INSULLATION OF OTHER FINISHES WITH LOXON BLOCK SURFACE LX01 SERIES, (50-100 SQ FT/GAL)
- 1ST COAT: S-W LOXON SELF CLEANING ACRYLIC COATING-SATIN, LX14-50 SERIES. 2ND COAT: S-W LOXON SELF CLEANING ACRYLIC COATING-GATIN, LX14-50 SEIRES (530-7.0 MLIS WET, 2.0-28 DRY PER COATI.
- F ALL EXTERIOR METALMORK, NOT GALVANIZED, SHALL BE PRIMED AND PAINTED WI 2 COATS OF EXTERIOR BYAMEL, PAINT, (UNITELS, BOLLARDS, ETC.) G CS SHALL VERIFY LOCAL JURISDICTION AND WIND SPEED REQUIREMENTS TO DETERMINE IF HURRACANE RATED HIGH IMPACT STOREFRONT OR SIGNINGS IS REQUIRED.



METAL -WALL PANEL



EXTERIOR COLORS AND FINISHES, REFER TO A401





Findings

Staff is seeking your review and recommendation on the following:

✓ Proposed building elevations and landscape design

Staff welcomes any feedback





Design Review Board