
# **Final Plat Vicinity Map**

## **Case Details**



#### **Project:**

Longbow Business Park & Golf Club Lot 2 Replat SUB25-00340

#### Site / Address:

District 5. 10± acres located approximately 1,180 feet west of the southwest corner of North Recker Road and East Longbow Parkway.

### **Description:**

Dover Associates LLC, Owner; Gary Stocker, Stocker Consulting, Surveyor

