



Legislation Details (With Text)

**File #:** DSN 24060  
**Type:** DSN Presentation      **Status:** Agenda Ready  
**In control:** Design Review Board

**On agenda:** 7/9/2024

**Title:** DRB24-00250 - "Valvoline Instant Oil Change Sossaman" (District 6). Within the 1300 block of South Sossaman Road (west side). Located south of Hampton Avenue and west of Sossaman Road (1± acres). Design Review for a minor automobile repair facility. Benjamin Tate, Withey Morris Baugh, PLC, Applicant; Avalon Sossaman, LLC, Owner.

Staff Planner: Tulili Tuiteleleapaga-Howard

**Sponsors:**

**Indexes:**

**Code sections:**

**Attachments:** 1. Vicinity Map, 2. Project Narrative, 3. Site Plan, 4. Landscape Plan, 5. Elevations, 6. Renderings, 7. Photometric Plan, 8. Wall Detail, 9. Presentation

| Date | Ver. | Action By | Action | Result |
|------|------|-----------|--------|--------|
|------|------|-----------|--------|--------|

**DRB24-00250 - "Valvoline Instant Oil Change Sossaman" (District 6).** Within the 1300 block of South Sossaman Road (west side). Located south of Hampton Avenue and west of Sossaman Road (1± acres). Design Review for a minor automobile repair facility. Benjamin Tate, Withey Morris Baugh, PLC, Applicant; Avalon Sossaman, LLC, Owner.

**Staff Planner: Tulili Tuiteleleapaga-Howard**