



## Legislation Details (With Text)

<b>File #:</b>	17-0946	<b>Status:</b>	Agenda Ready
<b>Type:</b>	Subdivision Plat	<b>In control:</b>	City Council
<b>On agenda:</b>	9/11/2017		
<b>Title:</b>	"Eastmark Development Unit 6-Infrastructure for Parcels 4-6 AND 9-23" (District 6) The 3900-4700 blocks of South Eastmark Parkway, the 9900-10200 blocks of East Point Twenty-Two Boulevard, and the 4000-4400 blocks of South Everton Terrace. Located north and east of Ray and Ellsworth Roads. 15 PCD landscape tracts (26.03± acres). DMB Mesa Proving Grounds, LLC, owner; Kenneth P. Converse, Hoskin Ryan Consultants, Inc., surveyor.		
<b>Sponsors:</b>			
<b>Indexes:</b>			
<b>Code sections:</b>			
<b>Attachments:</b>	1. Vicinity Map, 2. Council Memo, 3. Final Plat		

Date	Ver.	Action By	Action	Result
------	------	-----------	--------	--------

"Eastmark Development Unit 6-Infrastructure for Parcels 4-6 AND 9-23" (**District 6**) The 3900-4700 blocks of South Eastmark Parkway, the 9900-10200 blocks of East Point Twenty-Two Boulevard, and the 4000-4400 blocks of South Everton Terrace. Located north and east of Ray and Ellsworth Roads. 15 PCD landscape tracts (26.03± acres). DMB Mesa Proving Grounds, LLC, owner; Kenneth P. Converse, Hoskin Ryan Consultants, Inc., surveyor.