



Building Inspections Division

Certificate Of Completion

Record Number: PMT18-12955
Project Address: 4011 S POWER RD, MESA, AZ 85212
Project Description: PBI: REPAIRS TO NON-PERMITTED EXISTING STRUCTURES FOR ELECTRICAL AND MINOR PLUMBING.LIKE FOR LIKE, NO PLANS.
Owner Name:
Owner Address:

This Certificate is issued pursuant to the requirements of the Mesa Administrative Code, Section 4-1-6(C) which became effective March 3, 2008, certifying that on the date indicated, the work authorized under the Building Permit noted above has been satisfactorily completed and is in compliance with said Code (International Codes adopted by City of Mesa and in effect at the time of permit submittal) with various ordinances of the City regulating building construction insofar as ascertained by the undersigned.

This Certificate does not grant authority to occupy a building prior to the issuance of a Certificate of Occupancy. Any alterations or changes to the project for which this Certificate is issued shall void this Certificate.

Conditions/Restrictions:

No Conditions/Restrictions

Building Safety Director

09/25/2018

Date