**FDID:** 08183 **Alarm Date** 04/21/2022 Incident Number: F2022039710 **Time:** 16:45:38



### Mesa Fire and Medical Department Basic Fire Report

### **NFIRS - 1 Basic**

**Alarm Date Time:** 04/21/2022 16:45:38 Street Address: 121 E-E GARNET AVE-Avenue **Arrival Date Time:** 04/21/2022 16:50:49 City, State, Zip Code: Mesa, AZ 85210

Incident Cross S PIMA & E GROVE AVE **Controlled Date** Street: Time:

Last Unit Cleared 04/21/2022 18:48:51 **Incident Type:** 111-Building fire

Date Time:

Aid Given or 2-Automatic aid received

**Received:** 

**ESZ Zone:** 1500 Shifts or B Shift

Platoon:

**Primary Action** 11-Extinguishment by fire service

**Taken:** personnel

Resource Used: Y-Yes

**Civilian Casualties** 

**Civilian Casualty Severity** 

1-Minor

Property Use: 419-1 or 2 family dwelling

#### NFIRS - 2 Fire

This is N-This was Commercial: Residential

**Area of Fire Origin:** 26-Laundry area, wash house Cause of Ignition: 2-Unintentional

(laundry)

Heat Source: 80-Heat spread from another fire, Factors Contributing 10-Misuse of material or product,

other

to Ignition: other **Human Factors** 3-Unattended or unsupervised person **Item First Ignited:** 12-Exterior sidewall covering, surface,

> Contributing to finish Ignition:

**Type of Material First** 50-Natural product, other

Ignited:

### **NFIRS - 3 Structure Fire**

Total Number of 1 Main Floor Total 1500 **Structure Type:** 1-Enclosed building Square Feet:

Stories at or **Above Grade:** 

**Total Number of** 0 Building Status: 2-In normal use **Stories Below** 

Grade:

Story of Fire Origin: 1

Fire Spread: 3-Confined to floor of origin

Presence of 1-Present

**Detectors:** 

**Detector** 1-Fire too **Detector Type:** 1C-Smoke

detector Operation: small to not in the activate room/area detector

PO Box 1466 MS6060 Mesa, Arizona 85211 Ph (480) 644-3526 Fax (480) 644-3609

Alarm Date 04/21/2022 Time: 16:45:38 **FDID:** 08183

Presence of N-None **Automatic** Present Extinguishing System:

NFRIS - 9 Apparatus or Resource

Incident Number: F2022039710

THE STAPPOLOGIST OF RESOURCE					
<u>Apparatus</u>					
Apparatus or Resource ID	Apparatus or Resource Type	Apparatus or Resource Dispatch Date Time	Apparatus or Resource Arrival Date Time	Apparatus or Resource Clear Date Time	Apparatus Action
BC202	92-Chief officer car	16:45:38	17:00:36	17:36:39	
BC203	92-Chief officer car	16:53:23		16:55:49	93- Cancelled en route
BC252	92-Chief officer car	16:45:38	16:55:14	18:27:18	
BC271 (Mutual Aid Vehicle)	92-Chief officer car	16:51:16	17:01:59	17:19:40	
CON201	00-Other apparatus/resour ce	16:50:42	17:12:25	18:28:43	
E201	11-Engine	16:47:21	16:51:24	18:48:22	
E202	11-Engine	16:45:38	16:50:49	18:48:51	
E210	11-Engine	16:45:38	16:52:45	18:07:20	
E2510	11-Engine	16:45:38	17:00:46	18:13:32	
L201	12-Truck, Ladder Tender or Aerial	16:54:10	16:57:13	17:42:56	
L273	12-Truck, Ladder Tender or Aerial	16:46:02	17:00:28	17:48:28	
LT273	12-Truck, Ladder Tender or Aerial	16:46:02		16:46:46	93- Cancelled en route
M2202	76-ALS unit	16:50:42	16:56:23	18:13:13	
U251	62-Light and air unit	16:50:42	17:19:31	18:07:28	
U277	00-Other apparatus/resour ce	16:50:51	17:07:52	17:28:29	

# **Narrative**

Incident Number: F2022039710 Alarm Date Time: 04/21/2022 16:45:38

PO Box 1466 MS6060 Mesa, Arizona 85211 Ph (480) 644-3526 Fax (480) 644-3609 **FDID:** 08183 **Alarm Date** 04/21/2022 **Incident Number:** F2022039710

**Time:** 16:45:38

Primary Narrative: E202 responded to house fire that extended from grass burned by home owner on the side of the

house in back yard. Upon arrival E202 found light smoke coming from the back yard area. E202 took command and pulled an attack line to the back yard through the side gate. E202 assigned E201 Interior sector for search, rescue and fire control on the interior of the structure. E202 extinguished the fire on the outside of add-on laundry room and then pulled siding to check for extension. E201, Interior, gave a primary all clear report of the structure with no fire on the interior and light haze throughout structure. E202 noticed moderate brown smoke coming from the attic through vents and the gable end. E202 redirected attack line to the east end gable to perform a gable end attack. More hotspots and smoldering was extinguished by E202 while Interior pulled ceiling and checked for extension. Interior also performed salvage and overhaul. Fire was then called under control and loss stopped. E202 and BC252 met with home owners and explained the need to contact their insurance for further actions while assisting them with finding belongings. The home was then left to the homeowners. E202 and

rest of responding units went available.

Officer In Charge: Barrios, Benedict FIRE CAPTAIN 04/22/2022

## **Insurance and Loss**

Property Losses: \$20000 Property Pre- \$443600

Incident Value:

Content Losses: \$5000

PO Box 1466 MS6060 Mesa, Arizona 85211 Ph (480) 644-3526 Fax (480) 644-3609