



## Legislation Details

<b>File #:</b>	DSN 21016		
<b>Type:</b>	DSN Presentation	<b>Status:</b>	Agenda Ready
		<b>In control:</b>	Design Review Board
<b>On agenda:</b>	2/9/2021		
<b>Title:</b>	DRB20-00823 District 6. Within the 10700 block of East Guadalupe Road (south side). Located west of Signal Butte Road on the south side of Guadalupe Road. (0.8± acres). Requesting the review of an automobile/vehicle service and repair facility. Hayley Bancroft, GreenbergFarrow, applicant; Tina Kelty, KEMF GB PAD LLC, owner.		
	Staff Planner: Wahid Alam		
<b>Sponsors:</b>			
<b>Indexes:</b>			
<b>Code sections:</b>			
<b>Attachments:</b>	1. Vicinity Map, 2. Site Plan, 3. Landscape Plan, 4. Building Elevations, 5. Materials Board, 6. Floor Plan, 7. Sign Package, 8. Lighting, 9. Project Narrative, 10. Grading & Drainage, 11. Building Sections, 12. Presentation		

Date	Ver.	Action By	Action	Result
------	------	-----------	--------	--------